CHANGE ORDER FORM

08

CHANGE ORDER NUMBER

PROJECT: US 271: The construction of a new location, freeway facility consisting of grading, structures, base, surfacing & pavement markings from 0.3 miles north of US 67 to 0.6 miles south of FM 3417

CONTRACTOR: Williams Brothers Construction Co., Inc.

Contractor Is directed to make the following changes to the Contract Documents.
DESCRIPTION OF Add Safety Switch to all 480V Electrical Services per SWEPCO requirements
CHANGES: Remove & Reset 30" SET by Force Account
Reduce quantity for 36" Drilled Shaft due to plan error

ATTACHMENTS: See Separate List of Attachments

CHANGE IN CONTRACT P	RICE	CHANGE IN CONTRA		
1. Original Price:	\$ 72,825,618.51	Original Time:	663	DAYS
2. Total of Prior Change Orders:	\$ 471,348.05	Total of Prior Change Orders:	0	DAYS
3. Total Price Prior to Current Change Order:	\$ 73,296,966.57	Total Time Prior to Current Change Order:	663	DAYS
4. Total of Current Change Order:	\$ (1,246.00)	Total of Current Change Order:	0	DAYS
5. New Price Resulting from Current Change Order:	\$ 73,295,720.57	New Time Resulting from Current Change Order:	663	DAYS
AGREED BY:				
Williams Brothers Construction Co:	New D.	Fiter L.	03-	06-13
Jame	D. Pitcock, Jr., P.E.	Signature) Chairman and CEO		ate)
PTP Transportation, LLC:	/ Van R.K	e fak	3-8	
	(Signature)	(Da	ite)
APPROVED BY:	1.	21		
Titus County:	1 Sum	P. Lee	3-23	5-13

(Date)

Texas Department of Transportation:

Federal Highway	Administration:

(Signature)

(Signature)

(Signature)

(Date)

(Date)

			COST	REPC	DRT					
ltem N Item	umber Desc.	Description	Unit	u	nit Price	Authorized Quantity To Date	Change Order Quantity	Revised Quantity	Change Co	
Change O	rder 08									
9008	1001	ADD SAFETY SWITCH TO 480V ELEC SERVICE	ى	\$	6,754.08	0.00	1.00	1.00	\$	6,754
9008	2001	REMOVE & RESET 30" SET'S	LS	\$	999.92	0.00	1.00	1.00	\$	99
0416	2004	DRILL SHAFT (36 IN)	Ŀ	\$	150.00	8,981.00	-60.00	8,921,00	\$ ((9,00
				┨──						
										_
				\vdash						
		·		┨						
				┢						
				1					 	
		·		┢						
				-					 	
				+						



US 271 – Change Order 08 List of Attachments

- Letter to TxDOT Re: Change Order 08 Justification
- Letter to TxDOT Re: Change Order 08 Price Justification
- Letter to TxDOT Re: Change Order 08 Environmental Assurance Statement

Addition of Safety Switch to 480V Electric Service

- Williams Brothers Change Order Transmittal
 Williams Brothers Change Order Worksheet
- o Quote Letter from Texas Traffic Control Systems, Inc.
- o Material Quote from WE Manufacturing & Controls, Inc.

Remove & Reset 30" Safety End Treatments

- o Williams Brothers Change Order Worksheet
- o Pricing Breakdown from North Texas Contracting
- o Equipment Rental Rate Sheets
- o Material Quote for Cement Treated Sand
- o Email Thread Re: Remove & Relay SETS for PTP

Reduce Quantity for 36" Drilled Shaft

- o Revised Plansheets 810 & 812
- o Email from LJA Engineering Re: Abutment 9 Drilled Shafts
- o Email to Williams Brothers Re: Abutment 9 Drilled Shafts



February 22, 2013

Mr. Roger Ledbetter, P.E. Area Engineer – Mount Pleasant Texas Department of Transportation – Atlanta District 2210 W. Ferguson Mount Pleasant, Texas 75455

RE: Titus County CSJ: 0248-09-001, etc. US 271 Change Order 08 Justification

Dear Mr. Ledbetter:

PTP Transportation, LLC, on behalf of Titus County, is submitting for your review and approval Change Order 08 for the subject project. This change order is necessary to provide for payment for modifications or additions to several portions of the project. In summary form, the changes are:

- Addition of Safety Switch on 480V Electrical Services for Illumination
- Remove and Reset 30" Safety End Treatments
- · Reduce quantity of 36" Drilled Shaft

Addition of Safety Switch on 480V Electrical Services for Illumination

There are eleven services throughout the project that provide electrical connections for the safety illumination on the project. The subcontractor responsible for this work began coordination with Southwestern Electric Power Company (SWEPCO) for these services. SWEPCO informed them that on all services of 480 volts, they would require to have a safety disconnect switch before the electric meter for any future maintenance needs. This item provides for modifying the electrical services to include the safety switch for these services.

Remove and Reset 30" Safety End Treatments

The drainage culvert located at US 271 Station 344+81.03 has two Safety End Treatments (SET) on the downstream end of the culvert. These SETs were placed at the time of the culvert placement. After embankment fill and shaping of the area, it was determined that the skew angle of the culvert in relation to the roadway side slope created a roadway side slope that was too severe to be left. This work included the removal of the existing SET and then resetting it after additional pipe was laid.

Reduce Quantity of 36" Drilled Shaft

On the CR 2040 Overpass, it was determined that a typographical error on the bridge layout showed for Abutment 9 to have 9 drilled shafts. The correct number was 8, as confirmed by the design engineer. This change order is to reduce the quantity that was included incorrectly in the plans.

February 22, 2013 Mr. Roger Ledbetter US 271 Change Order 08 Price Justification Page 2

All of the costs associated with this change order are summarized in the Cost Report, included with this change order. If you have any questions regarding this matter, please feel free to contact me at (936) 441-9121.

Sincerely,

PTP TRANSPORTATION, LLC

Rich P. Kombergen P.E.

Richard L. Kronenberger, P.E. Assistant Director of Construction Services

Attachments cc: PTP Transportation, LLC Staff File



February 26, 2013

Mr. Roger Ledbetter, P.E. Area Engineer – Mount Pleasant Texas Department of Transportation – Atlanta District 2210 W. Ferguson Mount Pleasant, Texas 75455

RE: Titus County CSJ: 0248-09-001, etc. US 271 Change Order 08 Price Justification

Dear Mr. Ledbetter:

This letter serves as notice that the new pay items and prices below have been reviewed and are considered fair and reasonable for the subject project.

Item Number		Description	Unit	Unit Price
Item	Desc	Description	Unit	Onterfice
9008	1001	ADD SAFETY SWITCH TO 480V ELEC SERVICE	LS	\$6,754.08
9008	2001	REMOVE & RESET 30" SET'S	LS	\$999.92

This consideration is made based on the justifications provided for each consisting of quotes, previously established labor and equipment rates, and equipment rental rate sheets provided. Each item is described in greater detail below:

9008-1001 ADD SAFETY SWITCH TO 480V ELEC SERVICE

The documents included for this item include the material and freight quote provided from WE Manufacturing & Controls, Inc. (WEMC), a supplier to Texas Traffic Control System, Inc. (TTCS), a subcontractor to Williams Brothers Construction Company, Inc (WB). As a comparison of the quoted priced from WEMC, the material pricing was checked with a Houston-based commercial electrical supply, Wildcat Electric. Using a price quoted from them, the bare breaker switch was quoted at \$205.00 per each. The quoted priced from WEMC of \$405.00 per each also includes the separate panel and additional wiring to connect it to the electrical service unit. This additional work is reasonably believed to cost the additional amount. The markups of TTCS and WB are reasonable based on the project specification.

9008-2001 REMOVE & RESET 30" SET'S

The pricing for this work was established by using the labor, equipment and material rates of the existing crew on the project for North Texas Contracting (NTC), a subcontractor to WB. The labor rates used have been established through past change order work. The equipment rates for

February 26, 2013 Mr. Roger Ledbetter US 271 Change Order 08 Price Justification Page 2

the Foreman's vehicle and the Rubber Tire Loader have been previously established by past change order. The equipment rate for the Rubber Tire Backhoe is established through the equipment rental rate. The cost of the Cement Treated Sand is established through quoted price from WB, who is producing the material. The amount of work performed is reasonable for 2 1/2 hours. The markups included are reasonable based on the project specifications.

If you have any questions regarding this matter, please feel free to contact me at (936) 441-9121.

Sincerely,

Rich M. Komberger P.E.

Richard L. Kronenberger, P.E. Assistant Director of Construction Services

Attachments

cc: PTP Transportation, LLC Staff File



February 22, 2013

Mr. Roger Ledbetter, P.E. Area Engineer – Mount Pleasant Texas Department of Transportation – Atlanta District 2210 W. Ferguson Mount Pleasant, Texas 75455

RE: Titus County CSJ: 0248-09-001, etc. US 271 Change Order 08 Environmental Assurance Statement

Dear Mr. Ledbetter:

This letter is to serve as notice that the proposed work on this change order will not affect any of the environmental clearances or commitments for the subject project. The work included in this change order includes:

- Addition of Safety Switch to 480V Electrical Services
- Remove and Reset 30" Safety End Treatments
- Reduce quantity of 36" Drilled Shafts

If you have any questions regarding this matter, please feel free to contact me at (936) 441-9121.

Sincerely,

PTP TRANSPORTATION, LLC

Terry L. Plucker Director of Environmental Services

cc: PTP Transportation, LLC Staff File



CHANGE ORDER TRANSMITTAL

Williams Brothers Construction Company, Inc. P.O. Box 66428, Houston, Texas 77266 Phone: 713-522-9821 Fax: 713-520-5247

 Date:
 February 6, 2013

 Project:
 0248-09-001

 Control:
 0248-09-001

 Highway:
 US 271

 WB Job:
 475

For Office Use Only

Vanessa Wallace To: Contract Administrator PTP Transportation, LLC 1500 Research Forest Drive, Suite 106 The Woodlands, TX 77381

Attn: Mr. Jose Ramirez, P.E. Director of Construction Services Sent Via: DParcel Post

UPS
Federal Express
Courier
Other - Email

Dear Mr. Ramirez:

We are sending you the attached change order pricing with appropriate documentation. Your approval and initiation of the change order is requested.

☑ Titus County Requested □ Contractor Requested

Scope/Description:

Titus Co/TxDOT requested change order to add disconnects to the electrical services. If you have any questions regarding this matter, please call.

> Sincerely, WILLIAMS BROTHERS CONSTRUCTION COMPANY, INC.

Ehalzen

Seth Schulgen Vice President

Encls Change Order Estimate Subcontractor Estimate

Summary

.

U.\CHANGE ORDERS1475\Titus Co. CO - Service Disconnects - Job 475 (TTCS).xisx

							and the second second
	Change O		INSILEEL				
Service Disconnects	Qty:	1	ls				W8 47
0248-09-001							
0248-09-001							
US 271							
	1	SCOPE	l			1	
OT requested change order to add disconnects to t	he electrical servic	1			1		
					ĺ		
			SUE		WP	CC	
Description	UM	Est Qty	Unit \$	Ext\$	Unit\$	Ext \$	Remark
Description	1 0/01						
Description	- Unit				Acres 1		
	EA	11.00	506.25	5,568.75	536.88	5,905.68	
					536.88 848.40	5,905.68 848.40	
	Service Disconnects 0248-09-001 0248-09-001 US 271 00T requested change order to add disconnects to 1	Change O Service Disconnects Qty: 0248-09-001 0248-09-001 US 271 US 271 OT requested change order to add disconnects to the electrical service	Change Order Wo Service Disconnects Qty: 1 0248-09-001 0 0 0248-09-001 0 0 US 271 0 0 SCOPE OT requested change order to add disconnects to the electrical services. 0 0 0	Change Order Worksheet Service Disconnects Oty: 1 ls 0248-09-001 0248-09-001 0 0248-09-001 0 0 US 271 0 0 SCOPE OT requested change order to add disconnects to the electrical services. 00T requested change order to add disconnects to the electrical services. 0 SUE	Change Order Worksheet Service Disconnects Qty: 1 is 0248-09-001 0 0 0248-09-001 0 0 US 271 0 0 SCOPE OT requested change order to add disconnects to the electrical services. 0 0 0 0 0 0 SUB	Change Order Worksheet Service Disconnects Qty: 1 Is Is	Service Disconnects Qty: 1 is 0248-09-001 Image: Second service se

SCHULGEN

2/6/2013 4:40 PM

TEXAS TRAFFIC CONTROL SYSTEMS, INC. P.O. BOX 147, DIKE, TEXAS 75437 903-945-5129 FAX 877-543-5918

February 6, 2013

Williams Brothers Construction Co. P.O. Box 66428 Houston, Texas 77266-6428

RE: Titus County Project: 0248-09-001

At the meeting with Williams Brothers and PTP on Tuesday, Feb. 5, 2013 we were informed that all of the services for the lighting will need a disconnect ahead of the meter. Please see email on 1-23-13. The following is a breakdown for the change request to add these disconnects.

Material Only

W E Mfg.	11 ea	405.00	4,455.00
25%			1,113.75
Shipping (see Quote)			800.00
Total for change			6,368.75

If you have any questions please give me a call.

Sincerely,

atty & Kong

Cathy S. King President



Aanufacturing, & Controls, Inc. 5535 Harvey Wilson Drive Houston, Texas 77020 Phone: 713-676-2298 Fax: 713-676-1077 www.wemanufacturing.com

Quotation

\$4,455.00

Date 02/06/13 Quotation # 7478-R1

Quotation valid until: 03/08/13 Prepared by: Trevor Mitchell

Quoted to: Texas Traffic Control Systems, Inc. P.O. Box157 New Caney, Texas 77357

Attn: Cathy Item Code	Description	Unit Price	Qty.	Amount
	AEP Meter Disconnects on 480V Pedestals			
***	100A/2P 600V breaker with neutral block under an aluminum cover	\$405.00	11	\$4,455.00
	plate			
	Shipping using Wildcat's Central Freight account should be \$400 one			
	way for the 11 pedestals on 3 pallets from Dike, Texas to Houston,			
and the second	lotal round trip \$800.			

SHIPMENT: 2 TO 4 WEEKS A.R.O.

FOB Shipping Point with freight prepaid and allowed TOTAL All material remains the property of W E Manufacturing until paid in full If you have any questions concerning this quotation, contact Trevor Mitchell 832-325-2749

THANK YOU FOR YOUR BUSINESSI

CSJ 0248-09-001 Titus County US 271 WB 475

				Subcontra	actor Price	WB Markup	WB Bond	WB	Price
ltem	Description	UM	Qty	Unit \$	Extension	5%	1%	Unit \$	Extension
	REMOVE AND RESET 30" SET	LS	1.00 -	942.88 -	942.88 -	47.14 -	9.90 -	999.92	\$999.92
	TOTAL CHG ORDER								\$999.92

WORK DESC:

Cost to remove and reset 30" SET Revised 2/26/2013 - adj Equip & Material Pricing

This pricing provided constitutes an estimate of the work to be preformed based on the information provided by PTP. It should not be interpreted as a representative of actual cost.

PRICING BREAKDOWN - REMOVE & RELAY SET ON DOUBLE 30" RCP TITUS COUNTY US 271 PTP TRANSPORTATION / WILLIAMS BROTHERS CONSTRUCTION NORTH TEXAS CONTRACTING

LABOR BREAKDOWNS (.25 DAYS AT 10 HR'S / DAY W/ FOREMAN W/ 5 MAN CREW)

LABOR BREARDOWNS (.28 DAYS AT 10 HR S / DAY W	REGULAR HOURS CHARGED		LAR	OT HOURS CHARGED	c	RATES ADDED	L	TOTAL LABOR MOUNT
PROJECT MANAGER (OFFICE) PROJECT MANAGER (FIELD) SUPERINTENDENT (0) FOREMAN (1) OPERATOR (2) PIPE LAYER (1) PIPE LAYER (1) PIPE LABORER (1)	0.00 0.00 2.50 5.00 2.50 2.50 2.50 2.50	\$ 3 \$ 3 \$ 3 \$ 1 \$ 1 \$ 1 \$ 1	11.25 86.26 13.75 11.25 15.00 1.00 9.50		*****	61.88 54,39 50.63 46.88 22.50 19.50 16.50 14.25	\$ \$ \$ \$ \$ \$	78.13 75.00 32.50 27.50 23.75
EQUIPMENT BREAKDOWNS			S	SUBTOTAL LA	BOR		\$	236.88
COMPANY TRUCK / VEHICLE HAUL TRUCK DUMP TRUCK (TANDEM) (1.0 HR/ 8 CY LD) KOMATSU 308 TRACK EXCAVATOR CASE 580 (RBBR TIRE BACKHOE) KOMATSU WA250 R8BR TIRE LOADER 2YD INGERSOLL RAND SD-45 COMPACTOR COMPACTOR (JUMPING JACK) WATER TRUCK 6" WATER PUMP SMALL TOOLS / SUPPLIES	R R R R R R R R R R R R R R R R R R R	2.8 0 0 2.5 2.5 0 0 0 0 0 0 0 0 0	5	\$ 15.66 \$ 85.00 \$ 59.02 \$ 125.49 \$ 36.44 \$ 51.90 \$ 33.89 \$ 9.65 \$ 33.07 \$ 27.07 \$ 7.50	*****	39.15 91.10 129.75 - - - - - - - - -		
MATERIALS	UNIT	QUAN	אדו ד	UNIT PRICE		TOTAL		
CEMENT TREATED SAND	TN	6 SU		E 29.00		174.00 174.00		
SUBCONTRACTORS	UNIT	QUAN.	птү	UNIT PRICE		TOTAL		

			SUE	вто	TAL SUBCO	ONTRACTORS	\$	-
TOTALS & MARK UP SUMMARY		,	COST AMOUNT	_	URDEN 2)55 %	MARK UP %		TOTAL MOUNT
TOTAL LABOR AMOUNT TOTAL EQUIPMENT AMOUNT TOTAL MATERIALS AMOUNT TOTAL SUBCONTRACTOR AMOUNT		\$ \$ \$ \$	236.88 260.00 174.00	\$	130.28	25% 15% 25% 5%	\$ \$ \$ \$	426.38 299.00 217.50
	TOTALS	\$	670.88	\$	130.28		\$	942.88
				тот	AL ROUND	ED AMOUNT	\$	943.00

EQUIPMENT WATCH

www.equipmentwatch.com

Rental Rate Blue Book® Case 580M SERIES 2 (disc. 2008) Tractor-Loader-Backhoes Size Class: 14' to Under 15' 14' to Under 15' Weight 13,359 lbs. Configuration for 580M SERIES 2 Power Mode 4WD Diesel Drive Chill and 1.5 Loader Bucket Capacity-Heaped 1.00 cy Backhoe Stick Extendable Net Horsepower 76.0 Operator Protection EROPS Ser. Equipment Notes: Includes General Purpose loader bucket, backhoe bucket, and ROPS, unless otherwise noted. Blue Book Rates * FHWA Rate is equal to the monthly ownership cost divided by 176 plus the hourly estimated operating cost. and a start Del States Estimated Operating Costs **Ownership Costs** C.M. Martin Daily \$195.00 Monthly Weekly Hourty Hourty Published Rates \$2,790.00 \$780.00 \$29.00 \$22.35 Adjustments Region (Texas: 88.9%) (\$309.69) (\$86.58) (\$21.65) (\$3.22) Model Year (2008: 100%) -Ownership (100%) -Operating (100%) Total: \$2,480.31 \$173.35 \$693.42 \$25.78 \$22.35

Rate Element Allocation

-33

Set 3		
Element	Percentage	Value
Depreciation (ownership)	38%	\$1,060.20 / mo
Overhaul (ownership)	44%	\$1,227.60 / mo
CFC (ownership)	7%	\$195.30 / mo
Indirect (ownership)	11%	\$306.90 / mo
Fuel (operating) @ \$4.13	55%	\$12.21 / hr

Revised Date: 2nd Half 2012

All material herein @ 2003-2013 Penton Media, Inc. All rights reserved.

Page 1 of 1

February 26, 2013

FHWA Rate**

Hourty

\$38.20

\$36.44

EQUIPMENT WATCH

www.equipmentwatch.com

Rental Rate Blue Book®

Komatsu WA250PZ-6 4-Wd Articulated Wheel Loaders

Size Class: 135 - 149 HP 135 - 149 HP Weight: 27,778 lbs.

Configuration for WA250PZ-6

Power Mode	Diesel	Bucket Capacity - Heaped	3.00 cy
Net Horsepower	138.0	Operator Protection	EROPS

Equipment Notes: Includes General Purpose bucket and ROPS, unless otherwise noted.

Blue Book Rates ** FHWA Rate is equal to the monthly ownership cost divided by 176 plus the hourly estimated operating cost.

		Ownersh	lip Costs		Estimated Operating Costs	FHWA Rate*
	Monthly	Weekly	Dally	Hourly	Hourly	Hourly
Published Rates	\$4,140.00	\$1,160.00	\$290.00	\$44.00	\$31.30	\$54.8
Adjustments						
Region (Texas: 88.9%)	(\$459.54)	(\$128.76)	(\$32.19)	(\$4.88)		
Model Year (2010: 98.5%)	(\$55.21)	(\$15.47)	(\$3.87)	(\$0.59)	}	
Ownership (100%)	-	-	•	-		
Operating (100%)					· · ·	
Total:	\$3,625.25	\$1,015.77	\$253,94	\$38.53	\$31.30	\$51.90

Element	Percentage	Value
Depreciation (ownership)	45%	\$1,863.00 / mo
Overhaul (ownership)	36%	\$1,490.40 / mo
CFC (ownership)	8%	\$331.20 / mo
Indirect (ownership)	11%	\$455.40 / mo
Fuel (operating) @ \$4.13	59%	\$18.35 / hr

Revised Date: 2nd Half 2012

All material herein @ 2003-2012 Penton Media, Inc. All rights reserved.

Page 1 of 1



September 27, 2012



Date: November 1, 2011 Expiration Date: November 30, 2011



Williams Brothers Construction PO Box 66428 Houston, TX 77266 713.522.9821 Fax 713.520.5247 TO Zach Fusilier North Texas Contracting (NTC)

х.,

,

.

SALESPERSON	JOB 475-US271	SHIPPING	SHIPPING TERMS Delivered to	DELIVERY	State of the second	OUE DATE
Lanham	Titus County	Truck/Trailer	Job	·	Net 30 days.	<u> </u>
οτγ	ITEM#	DESCRIPTIO	ON UNI	TPRICE	DISCOUNT	LINE TOTAL
50,000 tons		Cem Stab 8	Bkfl (7%)	29	.00	
- 						
						5
120 80	Mart Area					
		an a				
		· · ·	244			C. F. Martin
			ss and se			
· ·	n. n. er - 6.			1.10 2		
				TOTAL DISCO	זאט	
					SUBTOTAL	
					SALES TAX	والرحة تستنشر مأتكر معتا
					TOTAL	

Quotation prepared by: Bob Lanham, President

.

This is a quotation on the goods named, subject to the conditions noted below. NA

Thenk you for your businessi

Craig Hill

From:	Jesse Khangura [JKhangura@wbctx.com]
Sent:	Wednesday, February 06, 2013 2:00 PM
То:	Craig Hill; Kathryn King
Cc:	Bob Lanham
Subject:	FW: Job 475: Titus County Back charges
Attachments:	REMOVE & RELAY SETS FOR PTP.pdf; ATT00001.htm
Follow Up Flag:	Follow up

Flag Status: Flagged

Categories:

Red Category

FYA

Jesse Khangura Vice President Williams Brothers Construction Co., Inc. <u>khangura@wbctx.com</u> Office 713-522-9821 Fax 713-522-5958 Cell 832-309-4194

From: Rick Kronenberger [mailto:rkronenberger@ptp.net] Sent: Wednesday, February 06, 2013 11:05 AM To: Jesse Khangura Cc: Jamie Voris; Robert Dick Subject: Fwd: Job 475: Titus County Back charges

This will be submitted as a change order. Prior to submitting, the labor calculation needs to be corrected. The 25% markup can not be applied to the labor burden.

Rick Kronenberger, P.E. Asst. Director of Construction Director of Design Services PTP Transportation, LLC 832.217.6014 (cell) rkronenberger@PTP.net

Begin forwarded message:

From: Robert Dick <<u>rdick@ptp.net</u>> Date: February 6, 2013, 10:23:58 AM CST To: Rick Kronenberger <<u>rkronenberger@ptp.net</u>> Subject: FW: Job 475: Titus County Back charges

FYI, see below from Jesse. Do you want him to submit as change order?

Robert C. Dick Jr. Chief Inspector PTP Transportation, LLC 1500 Research Forest Drive. Suite 200 The Woodlands, Texas 77381 Direct: 936-521-7130

1

Office: 936-441-9121 Fax: 936-539-9176 Cell: 936-672-3244 rdick@ptp.net

Mailing Address: P.O. Box 9389 The Woodlands, Texas 77387

From: Jesse Khangura [mailto:JKhangura@wbcix.com] Sent: Tuesday, February 05, 2013 9:11 PM To: Robert Dick Cc: Jamie Voris Subject: Job 475: Titus County Back charges

Bobby:

Do you want us to submit this a change order?

Jesse Khangura Vice President Williams Brothers Construction Co., inc. <u>ikhandura@wbotx.com</u> Office 713-522-9821 Fax 713-522-5958 Cell 832-309-4194

From: Jamie Voris [mailto:jamie@ntexcon.com] Sent: Tuesday, February 05, 2013 8:38 AM To: Jesse Khangura Cc: kking Subject: FW: Titus County Backcharges

Jesse:

Please see the attached T&M charges for removing and resetting the 30" SET's in Titus County. PTP paid the additional pipe quantity and CTS in January using our contract prices, we were able to reuse the SET's without damaging them which was my greatest concern. We also used a rubber tire 580 to excavate and rubber tire wheel loader to lift the SET's, this saved us from having to haul any equipment. These charges are only for removing and resetting the SET's.

Also attached is the charges to TJL for repairing the 24" that they damaged, for your record. Falready sent this to Jeff.

Thanks,

Jamie Voris Project Manager North Texas Contracting Cell: 817-819-0377 Fax: 817-430-9207 4999 Keller-Haslet Road Keller, TX 76248

From: Kathryn King [mailto:kking@ntexcon.com] Sent: Monday, February 04, 2013 1:33 PM

2

To: 'Jamie Voris' Subject: RE: Titus County Backcharges

Here are the change orders to submit. Please tell TJL that on their back charge we reduced our burden to 46% and only charged 15% markup.

From: Jamle Voris [mailto:jamie@ntexcon.com] Sent: Tuesday, January 29, 2013 2:03 PM To: kking Subject: Titus County Backcharges

Kathryn:


Here's the hours for the 30" SET's that we removed and reset for PTP under force account as well as the back charge to TJL for ripping through our 24" RCP. Will you look through them and adjust as you see fit.

Thanks,

Jamie Voris Project Manager North Texas Contracting Cell: 817-819-0377 Fax: 817-430-9207 4999 Keller-Haslet Road Keller, TX 76248

If the reader of this message is not the intended recipient, you are informed that any dissemination, copying or disclosure of the material contained herein, to include any attachments, in whole or in part, is strictly prohibited. If you have received this transmission in error, please notify the sender and purge this message. If attached, copies of documents that may be relied upon are limited to the printed copies (also known as hard copies) that are signed or sealed by the Engineer. Files in electronic media format or text, data, graphic or other types that are furnished by the Engineer are only for convenience of this e-mail recipient. Any conclusion or information obtained or derived from such electronic file will be at the user's sole risk. Furthermore, the electronic media is subject to change without notice and may not contain the most up-to-date information. When transferring documents in electronic media format, the Engineer makes no representations as to the compatibility, usability, or readability of the electronic media with the recipient's software application packages, operating systems or computer hardware.





												2.02/1	/01
HL 93 LOADING HL 93 LOADING HVI BAT BY ALL AND THVISTON 10174 ALL REVIEW, REV GUART 10174 ALL REVIEW REV GUART 10174 ALL REV GUART REV GUART	X	OSCAR R ACITING	ALLEN NO. 739	Under 10/2/2016		LUA Engineering, Inc. LA	of Transportation	US 271	BRIDGE QUANTITIES	CR 2040 OVERPASS	TOTAL TOTAL AID PROTECT AND TOTAL	6 atsmict county IEXAS ATLANTA TITUS	1 6906- CA 25401941505 0
		8644 8 414,639 418,569	95.44	116, 132	0 44 0 0 44 0	4 F 6 8	8544 8						026 j. j. j.
		66 44 7 115, 508 119, 242	BEAM 7	117.362	BEAU 7	115. 225	BEAN 7 412.765						
		6644 6 416, 361 419, 911	BEAM 6	416, 630	BEAM 6	015.211	86.44 5 415.315						
		8644 5 417, 199 <20, 578	BEAU		5 M 30	16.435	86 AM 5						
		65 M 4	BEAU &		8644 4 417 053		86.00 A						
11111111111111111111111111111111111111			BEAU 3					11 M99					
			BEAM 2					8644 10 411.124					
	4S	122.416 123.215 123.215						BEAU 9					
	ELEVATIONS	666 666 (666 66 (666 66)				100		₽ .4					
	SEAT ELE	85MT 6 19	5 5 7	•		,	BENT 9 1						
2. 206. 020	BEARING S	85.44 B	85 WM 8 423.588 423.460		BEAV 8 423.846 423.451		85.44 8 473, 384 419, 761		85,442 B				
	Ξ	122, 812	85AM 7 425, 624 423, 634		86444 7 424,190 423,880		BEAU 7 423, 851 420, 362		85 W 7				
		65.4M 5 422.856	BEAM 6 423. 832 423, 788		BEAN 6 424, 515 474, 297		BEAN 6 *24, 515 *20, 254		4F.AM & 418.456				
		85 AM 5 422, 850	9644 5 424.013 423.923	864M 13 472, 302	BEAN 5 424, 625 424, 688	122.072	86AU 5 424.119 421.540		80 m 5				
		86Au 4 422.836	80.44 4 474, 165 424, 039	0EAN 12 422, 573	8644 4 423.112 425.052	8EAN 12 422, 421	UEAN 4 125.241 122.117		88.244 4 419,869				
1 I NALUO		8644 3 422.784 8544 11 422.420	8644 3 424. 790 424. 135	86AM 11 422.515 422.823	8644 3 425. 383 425. 391	11 125 125	0544 3 425-702 422-680	BEAU 11	865.05A				
		86.44 2 422.704 86.44 10 422.563	BEAH 2 424, 387 424, 212	05 MM 10	BEAN 2 175.635 125.105	8544 10 423, 133 422, 603	864M 2 426.162 423.251	BEAN 10 422.447	6EAM 2 421.240				
		85.491 422.597 85.41 472.678	86 M 1 424. 456 424, 270	423.124		023.486 423.486 423.027	DEMU 1 424, 620 421, 809	864N 9 422.917 419.151	8644 1 421,911	BC5N 9 416.250			
		(F#0)	2 (8() (FWD)	(BX) (F WD)	3 (BK) (FWD)	(84) (01)	(86)	1041	~				
					-								

				ESTIN	MATED	QUANTI7	- 1ES		Aur	~
	0400-2005	0416-2001	0415-2004	0416-2005	0420-2041	0420-2042	0420-2062	0420-2256	0425-2063	2002-8510
LTEM	CEN STABIL	DRILL SHAFT	DHILL SHAFT	ORLL SHAFF	CL C CONC	UNER CONC	CL S CONC (HPC) REINF CONC SLAB	INPER SLABI	PRESTA CONC	CONC SUAF
LINGT	54	5	1	1	5	2	Sr	5	1	22
			Saver 1							
4 LI THAU	475	. 05	1 2.695.1	1.495	115.4	1.201.3	02.401	225	6. 638. 16	10, 199
			3							
			₽							

ESTIMATED QUANTILLES, CONT, D. A. (11, 2003, 2481-2013, 2013, 2014

 0412-2010
 0414-2015
 0414-2015
 0414-2015
 0414-2015
 0414-2015
 0414-2015
 0414-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 0415-2015
 <t

BENT

BENT BENT BENT BENT

\$182-6741 - 4466-5411 ExCanon

Rick Kronenberger

From: Sent: To: Subject: Daniel Copps <dcopps@ljaengineering.com> Friday, October 05, 2012 1:39 PM Rick Kronenberger Fw: CR 2040 Overpass

8 is the correct number.

Connected by DROID on Verizon Wireless

-----Original message-----From: William Dupal <<u>wdupal@ljaengineering.com</u>> To: Daniel Copps <<u>dcopps@ljaengineering.com</u>> Sent: Fri, Oct 5, 2012 16:07:26 GMT+00:00 Subject: CR 2040 Overpass

Dan,

According to Oscar Aguirre, it is a typo and there should only be 8 drilled shafts at Abutment 9.

1

William Dupal, P.E. Structural Engineer *LJA* Engineering, Inc. 2929 Briampark Drive, Suite 600 Houston, TX 77042-3703 Phone: (713) 953-5112 Fax: (713) 953-5183 E-mail: wdupal@ljaengineering.com

Rick Kronenberger

From: Sent: To: Cc: Subject: Rick Kronenberger Friday, October 05, 2012 7:55 PM inowbc@yahoo.com; Jesse Khangura (JKhangura@wbcbi.com) TitusCounty US 271 - CR 2040 Overpass - Abutment 9 Drilled Shafts

Ino & Jesse,

I wanted to confirm with you that the CR 2040 Overpass, Abutment 9 will have 8 drilled shafts. The label on the Bridge Layout Drawing (Profile View) is incorrect in stating 9. This abutment is to be built according the the linework/drawings shown on the Abutment 9 Detail sheet.

1

Please let me know if you have any questions. A revised Bridge Layout will be forthcoming.

Thanks,

Rick Kronenberger, PE

Assistant Director of Construction **PTP Transportation, LLC** 1500 Research Forest Drive, Suite 200 The Woodlands, Texas 77381 936.521.1467 Direct 936.441.9121 Main 936.539.9176 Fax 832.217.6014 Cell rkronenberger@ptp.net

Mailing Address: P. O. Box 9389 The Woodlands, Texas 77387

and the second