

Option 1

Estimate

East Texas Truck Systems
2283 Montgomery Gardens
Tyler, TX 75708 US
(903) 531-9700
david@easttexasrucksystems.com
www.easttexasrucksystems.com

ADDRESS
County of Titus

SHIP TO
County of Titus

ESTIMATE # DATE
1170 05/31/2017

SALES REP
JDR

| ACTIVITY | QTY | RATE | AMOUNT |
|--|-----|-----------|-----------|
| 2000 gallon water truck | 1 | 26,000.00 | 26,000.00 |
| Chassis: | | | |
| 1994 International 8100 | | | |
| Cummins L10 Engine | | | |
| 124,084 miles | | | |
| 10 Speed Manual Transmission | | | |
| 280 HP | | | |
| Tires 50% or Better | | | |
| Air Conditioning | | | |
| Truck Serviced | | | |
| DOT Inspected | | | |
| 2000 Gallon Tank System | | | |
| 5 Spray system - Air Activated | | | |
| Rear hydrant fill tube | | | |
| Front and rear sight level tubes | | | |
| Top load ducknest | | | |
| Rear ladder | | | |
| Shape: modified rectangular | | | |
| Tank exterior: blasted, primed, painted Sherwin-Williams gloss white paint | | | |
| Tank is spring mounted to truck chassis | | | |
| Tank mounted fenders | | | |
| Plumbing: | | | |
| 650 gpm water pump/ shaft driven | | | |
| Front Spraybar with two sprayers | | | |
| Rear Spraybar with two sprayers | | | |
| Side sprayer | | | |
| Control tower mounted inside cab to individually activate each sprayer | | | |
| 3" discharge at pump with camlock fitting | | | |
| 4" tank to pump supply with butterfly valve | | | |
| PTO: Muncie or Chelsea with tubular shaft from pump to PTO | | | |
| Bumper: push style bumper | | | |

Quote does not include delivery.

TOTAL

\$26,000.00

Accepted By

Accepted Date

Option 2

Estimate

East Texas Truck Systems
2283 Montgomery Gardens
Tyler, TX 75708 US
(903) 531-9700
david@easttexastrucksystems.com
www.easttexastrucksystems.com

ADDRESS
County of Titus

SHIP TO
County of Titus

ESTIMATE # DATE
1174 06/14/2017

SALES REP
JDR

| ACTIVITY | QTY | RATE | AMOUNT |
|---|-----|-----------|-----------|
| 2000 gallon water truck Chassis: 1991 International 8100 VIN: 1HSHBGBN1MH3185 352,590 miles 400 HP Tires 50% or Better Manual Transmission Cummins LTA10 Engine Truck Serviced DOT Inspected | 1 | 24,950.00 | 24,950.00 |
| 2000 gallon water tank system Shape: modified rectangular Carbon steel construction Top load ducknest Rear hydrant fill tube Rear ladder DOT lighting installed on tank Tank is spring mounted to truck chassis Tank Exterior: Painted Sherwin Williams white Mudflaps Fenders Plumbing: 650 gpm water pump--PTO driven Front spray bar with two sprayers Rear spray bar with two sprayers Side sprayer 3" discharge at pump with camlock fitting 4" supply from tank to pump with butterfly valve Control tower installed in cab -- individually activates sprayers--air activated Muncie PTO Tubular shaft from pump to PTO | | | |

Quote does not include delivery.

| | |
|--------------|--------------------|
| SUBTOTAL | 24,950.00 |
| TAX (0%) | 0.00 |
| TOTAL | \$24,950.00 |

Accepted By

Accepted Date


Bid to be opened 6/16/17 in court e. Jan
2 bid options are enclosed

PRESS FIRMLY TO SEAL

PRESS FIRMLY TO SEAL



1006



75455

U.S. POSTAGE
PAID
TYLER, TX
75702
JUN 14, 17
AMOUNT

\$6.65

R2305E126190-01

PRIORITY® ★ MAIL ★



DATE OF DELIVERY SPECIFIED*



USPS TRACKING™ INCLUDED*



INSURANCE INCLUDED*



PICKUP AVAILABLE

* Domestic only

Expected Delivery Day: 06/16/2017

USPS TRACKING NUMBER



9505 5120 2675 7165 0508 43



PS00001000014

EP14F July 2013

FR

PRIORITY® ★ MAIL ★



UNITED STATES
POSTAL SERVICE®

VISIT US AT USPS.COM®
ORDER FREE SUPPLIES ONLINE

Auditor Office
JUN 15 2017
Received
10:47

FROM: East TX Trk Systems
2283 Montgomery
Tyler, TX 75702

TO: Titus Co. Auditors Office
100 W. First St., Room 106
Mt. Pleasant, TX 75455

Label 228, July 2013

FOR DOMESTIC AND INTERNATIONAL USE

"Bid"

VISIT US AT USPS.COM®



UNITED STATES